


No-Braze OFS



FS-419
No-Braze OFS Sleeve


Use with FS-418 & FS-719

FS-419-① Part No.	① Tube O.D.	D Drill	L Length	X Diameter
FS-419-04	1/4	0.170	0.32	0.25
FS-419-06	3/8	0.260	0.34	0.38
FS-419-08	1/2	0.380	0.37	0.50
FS-419-10	5/8	0.480	0.40	0.63
FS-419-12	3/4	0.610	0.44	0.76
FS-419-16	1"	0.810	0.50	1.00
FS-419-20	1 1/4	1.050	0.56	1.26
FS-419-24	1 1/2	1.260	0.62	1.51

4:1 Safety Factor

No-Braze assembly information on page 174.

No-Braze OFS



FS-719
No-Braze OFS Ferrule

Use with FS-418 & FS-419

FS-719-① Part No.	① Tube O.D.	D Diameter	L Length
FS-719-04	1/4	0.26	0.25
FS-719-06	3/8	0.38	0.25
FS-719-08	1/2	0.51	0.30
FS-719-10	5/8	0.63	0.30
FS-719-12	3/4	0.76	0.30
FS-719-16	1"	1.01	0.30
FS-719-20	1 1/4	1.26	0.30
FS-719-24	1 1/2	1.51	0.30

4:1 Safety Factor

O-Ring
Face Seal